


AirFree® Technology & Automation

AirFree® technology acts as an additional axis when mounted on a benchtop automation system. The precise control engineered into the X, Y and Z axis is now applied to the fluid delivery axis. All axes are motor driven lead screws with known speeds and can be coordinated providing the highest precision and repeatability available on a benchtop robot.

Total Cost of Ownership

AirFree® Technology Adds Profits When Replacing Air Driven Systems



 Fishman Corporation
 192 South Street, Hopkinton, MA
 01748, United States

 US & Canada:
 800-433-2115
 Worldwide:
 1-508-435-2115
 www.fishmancorp.com

